

Snowmobilers in the Lionhead area got unstable test results, easily propagating fractures in ECT tests on a weak layer buried about 50 cm deep. Photo: J. Norlander

Advisory Region
Lionhead Range
Longitude
-111.30W
Latitude

44.70N

Forecast link: GNFAC Avalanche Forecast for Tue Feb 5, 2019GNFAC Avalanche Forecast for Wed Feb 6, 2019GNFAC Avalanche Forecast for Thu Feb 7, 2019
Lionhead Range, 2019-02-04