Targhee Pass Meadows **Andrew Schauer**
Henry Mtns **12/08/2019 - 12:00pm**
MT Co-ord: **44.68610N, -111.29080W**
Elevation: **8230 ft** Slope Angle: **28°**
Aspect: **30°** Wind Loading: **yes**
Specifics: **Collapsing, localized; Cracking**

Stability: **Very Poor** HS:**76** Layer Notes:
Air Temperature: 32-15cm:**Problematic layer**
Sky Cover: **OVC**
Precipitation: **S2**
Wind: **SW Moderate**



Notes: **Profile at fracture line of a slab that collapsed in DH layer (15-32cm) and propagated ~100'.**

Advisory Region
Lionhead Range
Longitude
-111.29W
Latitude
44.69N
Lionhead Range, 2019-12-08